

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

EC640 RESIDENCE MULTIPLE DWELLING  
ESE 500 BRIGHTWATER CT  
1/2-1 BROOKLYN, NY

NY LTANKS S120702896  
N/A

0.947 mi.  
5001 ft.

Site 2 of 3 in cluster EC

Relative:  
Higher

LTANKS:

Actual:  
8 ft.

Name: RESIDENCE MULTIPLE DWELLING  
Address: 500 BRIGHTWATER CT  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1610329 / Not Reported  
Facility ID: 1610329  
Site ID: 541146  
Spill Date: 2017-02-14  
Spill Cause: Tank Test Failure  
Spill Source: Commercial/Industrial  
Spill Class: Not reported  
Cleanup Ceased: Not reported  
SWIS: 2401  
Investigator: vszhune  
Referred To: Not reported  
Reported to Dept: 2017-02-14  
CID: Not reported  
Water Affected: Not reported  
Spill Notifier: Tank Tester  
Last Inspection: Not reported  
Recommended Penalty: False  
Meets Standard: False  
UST Involvement: False  
Remediation Phase: 1  
Date Entered In Computer: 2017-02-14  
Spill Record Last Update: 2017-06-27  
Spiller Name: CHRIS QUINTANO  
Spiller Company: RESIDENCE MULTIPLE DWELLING  
Spiller Address: 500 BRIGHTWATER CT  
Spiller County: 999  
Spiller Contact: CHRIS QUINTANO  
Spiller Phone: (718) 975-9363  
Spiller Extension: Not reported  
DEC Region: 2  
DER Facility ID: 494914  
DEC Memo: "02/14/17 - Lakhani The tank failed earlier this morning. All Boro was testing the tank and no noise was observed with the test. Water intrusion in the tank. Salt water is a problem in the area. They were unable to complete the test for salt water intrusion because it takes many hours. The test was rescheduled for another day. Nevertheless, there is a definite failure and could potentially be a hole in the tank. 3/23/17-Christ Quintana from All Boro sent the following email. Since the tank test failure at this location my company has not done any work at this property. They have been notified of the failure and the need to empty the tank and test further. The Management Company is: First Services Residential 212-634-8971 Antoinette Blankinship 718-943-9117"  
Remarks: "test failure"

All Materials:

Site ID: 541146  
Operable Unit ID: 1289715  
Operable Unit: 01  
Material ID: 2295477

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

|                |              |
|----------------|--------------|
| Material Code: | 0001A        |
| Material Name: | #2 fuel oil  |
| Case No.:      | Not reported |
| Material FA:   | Petroleum    |
| Quantity:      | Not reported |
| Units:         | Not reported |
| Recovered:     | Not reported |
| Oxygenate:     | Not reported |